

General Environmental Incident Summary

Incident: 4122 **Date/Time Notice:** 6/9/2016 0919 a **DEM Incident No:**
Responsible Party: Wolla Trucking LLC
Date Incident: 6/9/2016 **Time Incident:** 132 am **Duration:** 10 minutes
County: Williams **Twp:** 156 **Rng:** 100 **Sec:** 21 **Qtr:**
Lat: 48.32779 **Long:** -103.55590 **Method:** Interpolation from map
Location Description: Spill starts going south on county 9 off hwy 2, then turns east on county 8b approx. 3 miles.

Submitted By: Jason Wolla **Affiliation:**
Address: PO Box 830
City: Ray **State:** ND **Zip:** 58849

Received By:

Contact Person: Jason Wolla
PO BOX 830
Ray, ND 58849

Distance Nearest Occupied Building: 3 Miles **Release Contained:** No

Type of Incident: Tank Leak

Description of Released Contaminant: 13.5 Barrels of Produced Water

Volume Spilled: **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Support cable broke on truck causing a hose to drag on the ground and thus rubbing a hole in the hose.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Notify the department of health. Add an additional safety strap to ensure that if one breaks that we have another in place.

Wastes Disposal Location:

Agencies Involved: ND Oil and Gas

Updates

Date: 6/21/2016 ***Status:*** No Further Action Requested

Author: Torgerson, Brad

Updated Volume:

Notes:

At 3:15pm on 6/15/2016 I travelled the road surface of Williams County 9 from U.S. Hwy 2 to Williams County 8b and east for three miles and did not observe any obvious stains or spill impacted areas. No further corrective action or follow-up appears to be necessary.